10 0 1 0 1 07	INFO25X1A2g 9725Z CITE 3867			CITE		
IN 71077		0181-	PO P	See A See Assessment of the See Assessment o	allianne reges je diga rijeje se a opportunisti depistos po tapanja. Andriči ordin semanti senima kalenja kilomote, nam ujelje dij	and the second
TM 84088						
INFO :						
ACTION:						
FROM :			8	Challe (Challes Charles) - Montain et arrestamente de Augustus ( - Maria Charles Charles) - Montain (Maria Charles) - Mon	116)	PM 251
10 ,			5	ngint and the state of the stat	14 15	
		erik (1 markila magama mina kasifirah adalah da kasifiran yan magama (1 si da kasifiran da kasifiran da kasifir Da da haring kasifiran da kasifir	<u> </u>	en de la companya de	12 13	-
	and the state of t	THE RESIDENCE TO SERVE SAME LAW MAN AND AND AND AND AND AND AND ADDRESS OF THE PERSON	3	and appropriate to sometiment of the state o	71	Markey orton
DATE	<del></del>	- Tricket	<u> </u>		9 10	mat - contra

FOLLOWING INTEL SUMMARY SUBMITTED FOR MSN C-167C:

25X1A2g SURE THAT PODS WERE DROPPED IN THE PRE-DETERMINED AREA.

POD NBR 2 WAS DROPPED 49 SEC AFTER POD NBR 1. PYLONS WERE NOT

DROPPED AS PROGRAMMED BUT PILOT HELD DROP UNTIL WELL INTO MOUNTAINOUS

AREA. REASON FOR COURSE DEVIATION AFTER DROP WAS TO CONSERVE FUEL.

ADDITIONAL FUEL AND TIME WAS CONSUMED DURING EARLY PART OF FLT DUE

TO FACT THAT ARTICLE WAS PUTTING OUT HEAVY CONTRAILS DURING HOURS OF

LIGHT AND REPEATED TURNS WERE MADE TO DETECT ANY POSSIBLE ENEMY THREAT.

PILOT ELECTED TO PRESS ON EVEN THOUGH CONTRAILS AT THIS POINT FULLY

JUSTIFIED A MSN ABORT.

25X1D0e

DEDDONICTION BY OTHER THAN THE ICCIDENCE OFFICE IS TO CHARLE

## Approved For Release 2000/04/14 : CIA-RDP71B00263R000100070046-2

25X1A2g

IN 71077 3867

PAGE 2

(3) NO OTHER SIGNIFICANT DATA REPORTED.

S B S R B T TOR: 070833Z MAY 67